



# Die Performance von Passivhäusern



# 2 Passivhaus – Betriebserfahrungen



# Messergebnisse Passivhaus-Siedlung Hannover Kronsberg (32 WE)



Genauigkeit des Mittelwertes:  
 $\pm 6.6 / 32^{\frac{1}{2}} \text{ kWh}/(\text{m}^2\text{a}) = \pm 1.2 \text{ kWh}/(\text{m}^2\text{a})$

Zuluftheizung, Fernwärme

Streuung der Einzelwerte:  
 $\pm 6.6 \text{ kWh}/(\text{m}^2\text{a}) = 18.8\% \cdot 35.1 \text{ kWh}/(\text{m}^2\text{a})$

Bezug: Wohnfläche

# Passivhaus – Langzeiterfahrungen



Untersuchungen nach 25 Jahren Nutzung Passivhaus


*Health check after 25 yrs of occupation*




# Heizung ein Vierteljahrhundert Messwerte




# Komfort ein Vierteljahrhundert Messwerte




# 445 mm Mineralwolleddämmung: Grasdachaufbau als Warmdach im Passivhaus Kranichstein



# 445 mm Mineralwolleddämmung: Grasdachaufbau als Warmdach im Passivhaus Kranichstein



# 275 mm Wärmedämmverbundsystem auf Kalksandstein: Massivwandaufbau im Passivhaus Kranichstein



# 275 mm Wärmedämmverbundsystem auf Kalksandstein: Massivwandaufbau im Passivhaus Kranichstein

- Rohdichte 14,92(17) kg/m<sup>3</sup> ✓
- Druckfestigkeit EPS ( $\sigma_{10}$  59 kPa) ✓
- Wärmeleitfähigkeit EPS  
0,0412(12) W/(mK) ✓
- Dynamische Steifigkeit EPS
- Feuchtegehalt EPS  
überall < 0,5 Masse-Prozent ✓



# 275 mm Wärmedämmverbundsystem auf Kalksandstein: Massivwandaufbau im Passivhaus Kranichstein




Mineralische Putzschicht mit Armierungsgewebe

und Schwalbenschwanz-Nuten


Eindruck: „Betonplatte“

Druckfestigkeit 5,3 (1,3) N/mm<sup>2</sup>




„Gemäß dem super Zustand des Systems sollten weitere 25 Jahre kein Problem darstellen.“ Prof. Andreas Sixer; material sciences, UIBK


# Wärmebrückenfreie Konstruktion ... dauerhaft



# Wärmebrückenfreie Konstruktion ... dauerhaft



# Luftdichtheit: dauerhaft



Roof: PE-film

wall: gypsum-plaster

**JOINT: film overlapping,  
covered by gypsum**

1



**Fixing with  
plaster base**


2




**covered with  
plaster  
(longer humid)**

3

# Luftdichtheit: nach 25 Jahren




# Energie effiziente Fenster – 25 Jahre und mehr?




*Window panes have  
higher losses  
 $U$  some  $0,8 \text{ W/m}^2\text{K})$   
than the insulated  
wall*

*Gas losses?*

*Spacer  
performance?*



# Dreischeiben Wärmschutzverglasung: Gasverluste nach 25 Jahren?



*Costum made heat flow meter*

*Six  $U_g$  measured on site:*

$$Ug = 0,78(5) \text{ W}/(\text{m}^2\text{K})$$


*(Maximal value 0,97 W/(m<sup>2</sup>K))*

*Gas loss in av. lower than 0,25(10)%/a*

*In some cases (15%) 1,2(2)%/a*


***Result: with exceptions negligible gas loss;  
Life expectance for triple-low-e: 40 yrs***

# Balancierte Lüftung... hygienisch, hohe Innenluftqualität, effizient, dauerhaft




*Heat exchanger from the TEMOVEX heat recovery system. Running 25 yrs:*

- *still tight*
- *still highly efficient*
- *still clean*




*A close look into the clean fresh air filter box after 25 yrs (never cleaned!) F8-filters changed every year*

# Zulufttrakt: Hygiene: Dank F8-Filter sauber wie vor 25 Jahren



after 1 year

new




*The F8-Filter keeps the major part of all dust outside the system. Part of the dust are carbon particles and partially burned fuel – this is why the filter becomes black.*

*Supply air duct (silencer) – which has never been cleaned in 25 yrs and as still super-clean – as is the whole fresh air/supply air duct system; because of the F8 filter*

# Innenluftqualität

## Dauermessung CO<sub>2</sub> und Feuchte – in der Regel IDA2



Innenluftqualität  
Messkampagnen: Pilzsporen / spore count


*(almost) no CFU's in the fresh/supply-air*

*Indoor spore count: much less than outdoor*

*filters: no spores detected*

*Excellent indoor air quality IAQ  
... after 25 yrs no degradation*

# Effizienz Lüftung: Dauermessung Frisch-/Zu-/Ab- und Fortluft; WBG > 80%



# Zustand WR-Gerät und -Anlage

1) stabil 2) dicht 3) sauber 4) ...nochmal 25 a 5) Ventilator 20 a



*The system is:*

- 1) *undamaged: where is no special strain on any part except the ventilators*
- 2) *airtight*
- 3) *clean; also ducts are clean and undamaged*

*... all will last another 25 yrs. (LCC 50 a)*

*Except: The ventilators will have to be exchanged every 20 yrs.*